

SQUARE STYLE TACHOMETERS 2" & 3"

2AT5-2 TACH-Single 2-1/4" 5000 RPM
2AT3-2 TACH-Single 2-1/4" 3500 RPM
Ranges avail.: 0-2500, 0-3500, 0-5K, 0-6K
0-8K, 0-10K, 0-12K, 0-16K

33A-2 TACH-Single 3-1/8" 3500 RPM
35A-2 TACH-Single 3-1/8" 5000 RPM
Ranges avail.: 0-2500, 0-3500, 0-5K, 0-6K,
0-8K, 0-10K, 0-12K, 0-16K

TACH-Dual 2-1/4"
Ranges avail.: 0-3800, 0-4K, 0-5K, 0-6K,
0-10K, 0-16K

332TA1 TACH-Dual w/Synchro, 3-1/8" only
0-3500/12 or 24V
Ranges Avail.: 0-3500, 0-5K, 0-8K

Y33A-2 HOUR RPM - 3-1/8" 0-3500/0-5000
Ranges avail.: 0-3500, 0-5K, 0-7K, 0-10K

EXHAUST GAS TEMPERATURE SENDERS

('K' wire, chromel alumel)

712-2DWK, 1-1/4 to 2-1/2" clamp, 1" tip,
4' lead wire

712-2D, 1-1/4 to 2-1/2" clamp, 1" tip,
1' lead wire

712-2DWXX, 1-1/4 to 2-1/2" clamp, 1" tip,
20" lead wire

712-2ODW, 1-1/4 to 2-1/2" clamp, 1/2" tip,
4' lead wire

712-24D, 1-1/4 to 2" clamp, 1" tip,
1' lead wire

712-24DW, 1-1/4 to 2" clamp, 1" tip,
4' lead wire

712-36DW, 1-3/4 to 2-3/4" clamp, 1" tip,
4' lead wire

712-4D, 1/4 pipe thread, 4" tip,
4' lead wire

712-4D1, 3/8-24 thread, 2-1/2" tip,
4' lead wire

712-4D2, 1/8 pipe thread, 2-1/2" tip,
4' lead wire

712-4D3, 1/8 pipe thread, 6" tip,
4' lead wire

712-4D4, 1/4 pipe thread, 2-1/2" tip,
4' lead wire

CYLINDER HEAD TEMPERATURE SENDERS

('J' wire, iron constantan)

712-4W, 14mm ring, 4' lead wire

712-5W, 18mm ring, 4' lead wire

712-8W, 12mm ring, 4' lead wire

712-9W, 10mm ring, 4' lead wire

712-4, 14mm ring, 1' lead wire

712-5, 18mm ring, 1' lead wire

712-4WXX, 14mm ring, 20" lead wire

712-7D, 3/8-24 thread, 4' lead wire
2-1/2" tip

712-7DJ, 1/8 pipe thread, 4' lead wire
2-1/2" tip

712-7DK, 1/4 pipe thread, 4' lead wire
4" tip

712-7DH, 1/2 pipe thread, 4' lead wire
4" tip

TEMPERATURE SENDERS

399S, 1/8 pipe thread, terminal connection
(1/4" long tip)

399S1, 1/8 pipe thread, 4' lead wires
(1/4" long tip)

399S7, 1/8 pipe thread, foot lead wires
1" long tip)

399M, magnetic, 4' lead wires

399C, cement-on, 4' lead wires

399DS, dip stick, 4' lead wires

399S8-1, 1/4 pipe thread, 4' lead wires
(1" long tip)

399S9, 5/8-18 thread, 4' lead wires

(7/8" long tip- (lycoming & continental)

399W, 1/4-28 thread, 4' lead wires

(1/4" long tip- (carburetor temperature)

3990T, 1/4-28 thread, 4' lead wires

(1/4" long tip- (air temperature)

MISCELLANEOUS

light (186-12A2)

mag adapter (103-18)

24 volt adapter (329-24)

low power adapter (329-LPA)

fuse adapter (381)

MISCELLANEOUS TACHOMETER ACCESSORIES

light (specify red, green or clear)

fuse adapter (381)

magnet ring (rotor tachometer)

4 magnets, 732)

2 magnets, 731-

proximity sender (720-)

generator sender (303_ _ - (tach drive)

tang (for 303 gen. sender)

SWITCHES

255-16C, 2-position switch

255-16T, 2-position switch

254-20E, 4-position switch

254-21E, 6-position switch

254-20EDP, dual 4-position switch

254-21EDP, dual 6-position switch

254-23E, 3-position switch

254-12E, 8-position switch

254-13E, 9-position switch

SHUNTS

237-1 = 15 amp.

237-2 = 30 amp.

237-3 = 50 amp.

237-4 = 100 amp.

237-5 = 150 amp.

237-10 = 200 amp.

237-11 = 300 amp.

PRESSURE SENDERS

387-11MS 80 & 100

387-13MS 16#

LIGHT KITS

186-12A2, short green

186-12A2R, short red

186-12A2C, short clear

186-12A2L, long green

186-12A24L, long red

186-12A2CL, long clear

FUEL LEVEL SENDERS

395-5T

395-5S 4 inch to 1 foot deep tank

395-5S-1 12 inches to 2 foot deep tank